



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE BEFORE THE BOARD OF PATENT APPEALS AND INTERFERENCES

In re Application of:)
Woo Hyuk CHOI) Confirmation No.: 1083
Application No.: 09/843,781) Group Art Unit: 2871
Filed: April 30, 2001) Examiner: Z. Qi
For: REPAIR STRUCTURE FOR LIQUID CRYSTAL DISPLAY AND METHOD OF REPAIRING THE SAME) Mail Stop Appeal Brief-Patents)

Commissioner for Patents U.S. Patent and Trademark Office **Mail Stop Appeal Brief-Patents** Alexandria, VA 22315

APPELLANT'S REPLY BRIEF UNDER 37 C.F.R. § 1.193(b)(1)

Appellant filed a Notice of Appeal in the above-identified patent application on December 20, 2004. Appellant filed an Appeal Brief on February 16, 2005. This Reply Brief responds to the arguments raised in the Examiner's Answer mailed April 19, 2005. This Reply Brief is timely filed within the period for response which extends through Monday June 20, 2005 (June 19, being a Sunday).

Summary of Examiner's Answer

Based upon Appellant's arguments presented in the Appeal Brief filed on February 16, 2005, claims 1, 3-8, 17-19, 21-24, and 26 are now allowed. Accordingly, claims 9, 12, 15, and 16 stand rejected under 35 U.S.C. §103(a) as being unpatentable over <u>Salisbury</u> (US 5,303,074) in view of <u>Henley</u> (US 5,459,410).

Appellant's Reply Arguments

In the Examiner's Answer, the Examiner admits that "Salisbury does not explicitly disclose that the repair patterns bypasses to pixel electrodes adjacent to the data line." Thus, the Examiner relies upon Henley to reason that "[b]ecause the gate line (scan line) and the data line form the pixel region, as shown in Figs. 6 and 14, [sic] the repair pattern is a conductive bridge across the pixel region as shown in Fig. 12c." In addition, the Examiner alleges that "[t]he figures 6 and 14 show an electrical diagram that does not show the precise distance, and the figures show that the principle of the pixel [regions] are defined by the data line and the gate line." Furthermore, the Examiner concludes that "[t]herefore, when forming the conductive bridge, the repair pattern of the conductive bridge, inherently, [bypasses] to pixel electrodes adjacent to the data line." Appellant respectfully disagrees.

As admitted by the Examiner, "[t]he figures 6 and 14 show an electrical diagram that does not show the precise distance." However, FIGs. 6 and 14 are just that, electrical schematic diagrams that, by definition, are not meant to show exact relative positioning of individual components of the electric circuitry shown in FIGs. 6 and 14. Accordingly, Appellant respectfully asserts that no inference may be made as to placement of the conductive bridge 88, as shown in FIGs. 12a-12c, with regard to the electrical schematic diagrams of FIGs. 6 and 14.

Moreover, Appellant respectfully asserts that the Examiner's allegation that "the repair pattern of the conductive bridge, inherently, [bypasses] to pixel electrodes adjacent to the data line" is simple not true and definitely neither taught nor suggested by <u>Henley</u> or <u>Salisbury</u>, whether taken singly or combined.

With regard to the Examiner's dissertation on use of the term "bypass," Appellant respectfully asserts that the explanation is inapposite to either Henley or Salisbury, and fails to remedy the deficiencies of Salisbury, as admitted by the Examiner, or remedy the deficiencies of Henley, as presented above. Furthermore, Appellant respectfully asserts that the conclusion reached by the Examiner, i.e., "the repair pattern is a current shunt, and the repair pattern disclosed in Salisbury and Henley adjacent to the pixel electrodes and the data line, so that the repair pattern disclosed in Salisbury and Henley is bypassed to the pixel electrodes adjacent to the data line" is unsupported by any of Salisbury, Henley, or Merriam-Webster's Collegiate Dictionary, whether taken singly or combined.

The Examiner's Answer continues to allege that "Henley indicates (col. 2, lines 15-18) such repair structure [improves] the production yields, especially, for assembling high density active matrix LCD panels." Although Appellant does not dispute that Henley teaches inspection and repair of AM-LCD panels at col. 2, lines 15-18, Appellant does assert that Henley simply does not provide any teaching or suggestion, either implicitly or explicitly, that the conductive bridge structure 88, in FIGs. 12a-12c, overlaps or bypasses to the schematic representations of pixel electrodes shown in FIGs. 6 and 14 of Henley. More generally, Appellant respectfully asserts that Henley fails to teach, suggest, or imply that the conductive bridge structure overlaps or bypasses to any of the schematic representations of pixel electrodes disclosed by Henley.

The Examiner's Answer concludes that "it would have been obvious to those skilled in the art at the time the invention was made to arrange a repair pattern as claimed in claim 9 for improving the production yields of the high density active matrix LCD display." However, for at least the reasons set forth above, Appellant respectfully asserts that the Examiner fails to establish a *prima facie* case of obviousness with regard to independent claim 9, and hence dependent claims 12, 15, and 16. Specifically, Appellant respectfully asserts that the Examiner has failed to provide any proper motivation with which to modify <u>Salisbury</u> to arrive at the invention of independent claim 9, or any logical reasoning, based upon <u>Henley</u>, to modify <u>Salisbury</u> to arrive at Appellant's claimed invention.

Thus, at least for the reasons discussed above and those set forth in the Appeal Brief, Appellant respectfully submits that the rejection of claims 9, 12, 15, and 16 under 35 U.S.C. § 103(a) is improper and should be withdrawn.

CONCLUSION

In view of the foregoing, Appellant respectfully requests the reversal of the Examiner's rejections and allowance of all the pending claims. If there are any other fees due in connection with the filing of this Reply Brief, please charge the fees to our Deposit Account No. 50-0310.

Respectfully submitted,

MORGAN LEWIS & BOCKIUS LLP

Bv:

David B. Hardy Reg. No. 47,362

Dated: June 17, 2005

CUSTOMER NO. 009629
MORGAN, LEWIS & BOCKIUS LLP
1111 Pennsylvania Avenue, N.W.
Washington, D.C. 20004
Telephone: (202) 739-3000

Telephone: (202) 739-3000 Facsimile: (202) 739-3001